

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

Sacramento River Basin

MA0004	Overall LMA Rating	Total LMA Miles				
Maintenance Area 0004	A	3.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments					1.92	
Animal Control	0.01		0.01	0.29%		
<i>LMA Totals:</i>	0.01	0.00	0.01	0.29%	1.92	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2008 Levee Inspection Results

Maintenance Area 0004

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

Maintenance Area 0004

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	3.40
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/18/2008		9/22/2008	
DWR Inspector	John Williamson		John Williamson	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Maintenance Area 0004

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 Sacramento River							Right	3.40	09/22/2008	John Williamson	
LMR Line	Levee Mile		Category	Item	* Location	* Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.03	0.03	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.596705 ° -121.547397 °	38.596705 ° -121.547397 °		3
2	0.26	0.71	Earthen Levee	Encroachments	CR	PO	Buildings Inspector Comments: Corp. of Engineers Maint. Yard L.M. .26-.42; Dept. of Water Resource Sac. Maint. Yard L.M. .42-.71	38.596947 ° -121.543080 °	38.601188 ° -121.536622 °	Y	4
3	1.28	1.95	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: The Rivers housing development	38.602682 ° -121.526213 °	38.600412 ° -121.514403 °		7
4	1.33	1.48	Earthen Levee	Encroachments	CR	PO	Buildings Inspector Comments: The Rivers housing development houses on crown of levee waterside	38.602747 ° -121.525323 °	38.602583 ° -121.522412 °		8
5	2.03	2.12	Earthen Levee	Encroachments	LS	PO	Landscaping	38.599327 ° -121.513755 °	38.598148 ° -121.512910 °		14
6	3.07	3.30	Earthen Levee	Encroachments	LS	PO	Buildings	38.585640 ° -121.508383 °	38.582230 ° -121.509110 °		13
7	3.07	3.40	Earthen Levee	Encroachments	WS	PO	Landscaping	38.585642 ° -121.508385 °	38.534710 ° -121.517390 °		12

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Maintenance Area 0004

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Right	3.40	09/22/2008	John Williamson

Levee Mile Report Line	2
Start Levee Mile	0.26
End Levee Mile	0.71
Location	
Category	Earthen Levee
Item	Encroachments
Corp. of Engineers fence across levee blocking levee crown	



Levee Mile Report Line	2
Start Levee Mile	0.26
End Levee Mile	0.71
Location	
Category	Earthen Levee
Item	Encroachments
Corp of Engineers fence down waterside slope small walk thru gate at toe un able to inspect	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected